## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,775,880 B2

Page 1 of 1

DATED

: August 17, 2004 INVENTOR(S) : Gary A. Kasper et al.

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 14,

Line 21, reads "wherein the quick connect is a bayonet connection." should read -- wherein the quick connect mechanism is a bayonet connection. --

Signed and Sealed this

Thirtieth Day of November, 2004

JON W. DUDAS Director of the United States Patent and Trademark Office